## Annexure D

## BUILDING SAFETY CERTIFICATE

## No. 22/2/2025

## Dated: .23 04125

It is certified that the existing building Dawn Vasco School (name of the building or premises) at Amhat Alias Bairihwa, Malviya Road, Basti (U.P.) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	G+3 3 Floors 01					и.,

The building is owned/occupied by Dawn Vasco School (nameof the Institution) have complied with the Luilding safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD, (PUBLIC WORK DEPARMENT), Basti (Name of Department/ Govt.) on 23/04/2025 (date of inspection) in the presence of Rajesh Kumar Mishra, R/o Khirighat, Gandhi Nagar, Basti (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from I To X for a period of 2 years in accordance with rule and subject to compliance of the specific conditions as appendepd.

1.All NBC Conditions are follow by the institution.

2. In the Period of this certificate all NBC safety points are follow by institution.

3. This Period if any problem due NBC the department are not responsible

4. This Period if any problem due to NBC the institution are responsible all situations.

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail

Signature with Seal : अधिशासी आमयता ग्रामीण अभियंत्रण विभारित Name : Es ANK BER MA

Designation : ACSISTANT ENGINEER (14

Name & Address of Department/ Office: PWD, BASTI

68 |

CO SCHOOL DAWN VAS BASTI

DAWN VASCO SCHOOL BASTI